# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

#### HEARING COMPUTER SCHEDULED

CASE NO: CE03080423 3257 DAVIE BLVD CASE ADDR:

OWNER: ANSTER PLAZA AS INSPECTOR: THOMAS CLEMENTS ANSTER PLAZA ASSOCIATES

VIOLATIONS: NFPA 1 13-3.2.2

THERE IS NO HOOD PROTECTION PROVIDED OVER PORK ROASTER.

CE03022088 CASE ADDR: 3623 DAVIE BLVD

OWNER: GLASTON, H & MINERVA L

INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-25.3 A.3.d.iv.

THE REQUIRED PHYSICAL BARRIER FOR THE PURPOSE OF A BUFFER BETWEEN RESIDENTIAL AND COMMERCIAL PROPERTIES HAS NOT BEEN PROVIDED.

FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT OBTAINING THE RE-QUIRED PERMITS; ROOF RAFTERS ON THE NORTHEAST CORNER OF THE ROOF AT 3623 HAVE BEEN REPAIRED, A SHORT WALL CONSTRUCTED ON THE EAST END OF THE BUILDING DESIGNED TO PREVENT ACCESS TO THE ALLEY BETWEEN BUILDINGS AND AN AWNING STRUCTURE ATTACHED TO THE REAR OF 3623.

# FBC 104.2.11

VENTILATION WORK HAS BEEN DONE WITHOUT OBTAINING THE RE-QUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A FAN INSTALLED AT THE REAR OF 3625 (GATOR TINT) AND AN AIR CONDITIONING UNIT INSTALLED AT THE REAR OF 3623.

#### FBC 104.2.4

PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: WASTE PIPING ON THE REAR EXTERIOR WALL OF 3635 WHICH DRAINS OUT ON THE GROUND, AND NEW SUPPLY PIPING ON THE REAR WALL OF 3625 (GATOR TINT).

#### FBC 104.2.5

CIRCUITS HAVE BEEN ADDED TO THE EXISTING BUILDINGS ELEC-TRICAL SYSTEM WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A CIRCUIT FOR A FAN AT THE REAR OF 3635 AND A CIRCUIT FOR AN OUTSIDE LIGHT AT THE REAR OF 3635.

### FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED IN A SAFE CONDITION BY REASON OF WORK DONE WITHOUT PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: IMPROPER ROOF REPAIRS AND UNSAFE AWNING STRUCTURE (REAR) AT 3623 AND A SHORT WALL CONNECTING THIS BUILDING TO THE ADJOINING BUILDING ON THE EAST.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE03062263 CASE ADDR: 729 NW 7 TER

OWNER: ROY, DAVID & JIWANI RADHI

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.1

THE FOLLOWING BUILDING ALTERATIONS/CONSTRUCTION WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. A NEW OVERHEAD DOOR INSTALLED, AN AUTOMOBILE LIFTING DEVICE USED FOR SERVICE INSTALLED, AN ELEVATED STORAGE FLOOR COMPLETE WITH STAIRWAY CONSTRUCTED AND WALLS CONSTRUCTED TO PARTITION OFF OFFICES FROM THE REST OF THE BUILDING.

FBC 104.2.5

NEW CIRCUITS HAVE BEEN INSTALLED FOR THE OFFICES, THE LIFTING DEVICE AND LIGHTING WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC,M 401.2

THE BUILDING IS BEING UTILIZED FOR THE AUTO REPAIR. MANY VEHICLES ARE INSIDE THE BUILDING WITHOUT THE VENTILATION REQUIRED BY 403.3.

FBC 104.2.11

THE AIR CONDITIONING SYSTEM FOR THE OFFICES EXIST WITHOUT HAVING OBTAINED THE REQUIRED PERMITS AND INSPECTIONS.

FBC 3401.6

SPRAY PAINTING IS BEING DONE INSIDE THE BUILDING CONTRARY TO THE REQUIREMENTS OF THE FIRE PREVENTION CODE (NFPA 33). THIS PRESENTS AN UNACCEPTBLE HAZARD.

AUTOMOBILES INSIDE THE BUILDING WITHOUT THE REQUIRED VEN-TILATION PRESENTS AN UNACCEPTABLE HAZARD.

THE STAIRWAY, ELEVATED STORAGE AREA, AND AUTOMOBILE LIFTING DEVICE ALL PRESENT AN UNACCEPTABLE HAZARD.

ONLY ONE PROPER EXIT EXISTS FOR THE ENTIRE AREA OF 13,000 SOUARE FEET AND THE OFFICES EXIT THROUGH THE AUTOMOBILE SERVICE AREA. THESE CONDITIONS ARE CONTRARY TO THE EXITING REQUIREMENTS.

\_\_\_\_\_\_

#### RETURN HEARING (OLD BUSINESS)

CASE NO: CE03030532

CASE ADDR: 1919 NW 19 ST # 104
OWNER: PARKWAY COMMERCE CENTER LTD

INSPECTOR: STEVE PAINE

VIOLATIONS: FBC 104.1.1

THERE IS NO BUILDING PERMIT FOR NEW OFFICE AREA.

NFPA 1 1-10.1

EXIT LIGHTS AND EMERGENCY LIGHTS ARE NOT BEING MAINTAINED

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM - CITY HALL
AUGUST 26, 2003
10:00AM

THROUGHOUT.

NFPA 1 7-6.1.1

THERE ARE NO PORTABLE FIRE EXTINGUISHERS FOUND.

NFPA 13 3-2.6.3

THERE ARE PAINTED FIRE SPRINKLER HEADS INSIDE THE OFFICE AREA.

NFPA 13 5-1.1

FIRE SPRINKLER HEADS ARE MISSING INSIDE OFFICE AREA.

NFPA 101 4.5.3.2

THE NORTH EXIT DOOR IN WAREHOUSE IS BLOCKED BY STORAGE.

\_\_\_\_\_

CASE NO: CE03030533

CASE ADDR: 1919 NW 19 ST # 1A \*REQUEST FOR EXTENSION OF TIME\*

OWNER: PARKWAY COMMERCE CENTER LTD

INSPECTOR: STEVE PAINE

VIOLATIONS: FBC 104.1.1

THERE IS NO BUILDING PERMIT FOR THE 2ND FLOOR OFFICE.

NFPA 1 1-4.5

COVER(S) ARE MISSING ON ELECTRICAL OUTLETS THROUGHOUT

BUILDING.

NFPA 10 4-4.1

FIRE EXTINGUISHER(S) ARE NOT MAINTAINED ANNUALLY.

NFPA 13 5-1.1

FIRE SPRINKLER HEADS ARE MISSING FROM BOTH THE FIRST AND 2ND FLOOR OFFICES AND STORAGE AREA.

NFPA 1 1-10.1

EMERGENCY LIGHTS AND EXIT LIGHTS ARE NOT MAINTAINED IN

WORKING ORDER.

FIRE RATED OCCUPANT WALL IS NOT MAINTAINED IN SAFE

CONDITION.

\_\_\_\_\_\_

CASE NO: CE03040379

CASE ADDR: 1919 NW 19 ST \*REQUEST FOR EXTENSION OF TIME\*

OWNER: PARKWAY COMMERCE CENTER LTD

INSPECTOR: STEVE PAINE

VIOLATIONS: NFPA 1 7-3.1.1

THE FIRE SPRINKLER SYSTEM IS NOT MAINTAINED TO WORKING

ORDER.

NFPA 13 3-9.2

THE LISTED CAPS ARE MISSING ON THE FIRE DEPARTMENT SPRINKLER

CONNECTION.

NFPA 13 3-2.9.2

THE APPROVED SPRINKLER WRENCH IS MISSING FROM THE REPAIR

KIT.

\*REQUEST FOR ABATEMENT OF FINES\*

#### AGENDA

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003 10:00AM

NFPA 1 3-7.1

ADDRESS BAY NUMBERS ARE MISSING FROM THE DOORS.

NFPA 101 8.2.3.1.2

THERE IS NO FIRE RESISTIVE RATED WALL BETWEEN OCCUPANTS.

\_\_\_\_\_\_

RETURN HEARING (OLD BUSINESS)

CASE NO: CE01030696

CASE ADDR: 15 SE 11 AV
OWNER: STAFFELD, WILLIAM
INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 15-28

THE OWNER IS OPERATING A BUSINESS INSIDE HIS FRONT PROPERTY

WITHOUT AN OCCUPATIONAL LICENSE.

301(a)

THERE HAS BEEN MAJOR INTERIOR REMODELING DONE AT THE REAR BUILDING OF THIS PROPERTY WHICH INCLUDES BUT NOT LIMITED TO:

- 1. ALL THE DRYWALL HAS BEEN REMOVED FROM ALL THE INTERIOR WALLS.
- 2. THERE HAS BEEN NEW INTERIOR WALLS FRAMED
- 3. WINDOWS HAVE BEEN REMOVED
- 4. THE FRONT ROOF HAS BEEN PARTIALLY REMOVED
- 5. A NEW ENTRANCEWAY IS BEING FRAMED
- 6. NEW WINDOWS AND DOORWAYS ARE BEING FRAMED

301.1(d)

THERE HAS BEEN NEW PLUMBING LINES INSTALLED AND ALL THE OLD PLUMBINGS FIXTURES HAVE BEEN REMOVED ALL WITHOUT A PLUMBING PERMIT.

301.1(e)

THERE HAS BEEN NEW ELECTRICAL WIRING INSTALLED AND OLD

WIRING AND FIXTURES REMOVED WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

301.1(k)

THERE HAS BEEN NEW DUCT WORK INSTALLED ALL WITHOUT A PERMIT.

-----

CASE NO: CE01060795 CASE ADDR: 1951 NW 9 AVE

VE \*REQUEST FOR ABATEMENT OF FINES\*

OWNER: AMERICAN FEDERATED TITLE CORP

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 301(a)

BUILT A BAR OUTSIDE IN THE REAR OF THE BUILDING, ALTERED THE INTERIOR OF BUILDING WITH NEW WALLS COVERED WITH PLYWOOD,

ALL WITHOUT PERMITS.

301.1(e)

INSTALLED EXTERIOR ELECTRIC TO THE BAR OUTSIDE, WITHOUT

PERMITS.

#### Page

## AGENDA CODE ENFORCEMENT BOARD

#### CITY COMMISSION MEETING ROOM - CITY HALL

AUGUST 26, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE99080128

CASE ADDR: 449 NE 01 AV \*REQUEST FOR ABATEMENT OF FINES\*

OWNER: BRASSINGTON, PAUL D INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 105.1(a)

WOOD FENCE ON NORTH SIDE OF PROPERTY IS FALLING DOWN AND IS A WINDSTORM HAZARD. CARPORT FRAMING IS ROTTING.

#### HEARING COMPUTER SCHEDULED

CASE NO: CE03071272 CASE ADDR: 1417 N DIXIE HWY OWNER: CHOWDHURY, SHAHID M INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.2.7

INSTALLED SIGNS ON THIS CONVENIENCE STORE, ON THE WALLS AND

WINDOWS WITHOUT PERMITS.

CASE NO: CE03071273 CASE ADDR: 707 NE 13 ST CHOWDHURY, SHAHID OWNER: INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 47-22.3 R.

INSTALLED SIGNS ON THIS CONVENIENCE STORE, ON THE WALLS AND

\*\*REOUEST FOR ABATEMENT OF FINES\*\*

WINDOWS WITHOUT PERMITS.

## RETURN HEARING (OLD BUSINESS)

CASE NO: CE02091628

CASE ADDR: 6001 NW 29 AV AIRMARK ENGINES INC OWNER .

INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 40.3.4.1

THERE IS NO FIRE ALARM PROVIDED.

\_\_\_\_\_\_

CE02121828 CASE NO:

CASE ADDR: 5401 E PERIMETER RD \*\*REOUEST FOR ABATEMENT OF FINES\*\*

PERSONAL JET CENTER, INC OWNER:

INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 7.2.1.5.1

SLIDE BOLT AND HASP IS ATTACHED TO EXIT DOOR BLOCKING ACCESS TO EXIT FROM HANGAR THROUGH OFFICE. KEYED LOCK IS ATTACHED

TO EXIT DOOR BLOCKING ACCESS TO THE LEGAL EXIT.

NFPA 101 7.10.1.2

ILLUMINATED EXIT SIGNS ARE NOT PROVIDED DIRECTING EGRESS

THROUGHOUT.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

NFPA 101 7.9.2.1

THERE ARE NO EMERGENCY LIGHTS PROVIDED TO ILLUMINATE IN THE EVENT OF POWER FAILURE THROUGHOUT.

NFPA 1 6-1.5

EXTENSION CORD IS BEING USED AS PERMANENT WIRING SUPPLYING POWER TO AIR COMPRESSOR.

NFPA 101 39.2.4.2

THERE IS NOT A SECOND MEANS OF EGRESS LEADING FROM THE HANGAR.

NFPA 101 7.2.1.8.1

SELF-CLOSING DEVICE IS MISSING FROM FIRE DOOR LEADING FROM HANGAR THROUGH OFFICE.

#### HEARING COMPUTER SCHEDULED

CASE NO: CE03080512 CASE ADDR: 2901 NW 62 ST
OWNER: BLANTON LAND TRUST #1001

INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 7.9.2.2

THE EMERGENCY LIGHTS DO NOT ILLUMINATE IN THE CAFETERIA AND

WEST HALLWAY.

SFM 4A-48.005(2)(a)

THE FIRE ALARM IS NOT PROPERLY MAINTAINED.

NFPA 1 1-10.1

THE STROBE LIGHTS IN THE BACK SECTION, LOSS PREVENTION AND

WEST EXIT DO NOT ILLUMINATE.

\_\_\_\_\_

CASE NO: CE03080521 CASE ADDR: 1300 W MCNAB RD

MC NAB INDUSTRIAL PLAZA

INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 10 4-4.1

FIRE EXTINGUISHERS ARE PAST DUE FOR ANNUAL SERVICE.

NFPA 1 1-10.1

THERE IS NO FIRE PROTECTION FOR PARTS CLEANER.

CASE NO: CE03080523 CASE ADDR: 6720 NW 15 WY
OWNER: PACE INDUSTRIES INC

INSPECTOR: IVETT SPENCE-BROWN

VIOLATIONS: NFPA 101 39.2.4.2

SECOND FLOOR DOES NOT HAVE A LEGAL EXIT.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

RETURN HEARING (OLD BUSINESS)

CASE NO: CE03011765

CASE ADDR: 909 BREAKERS AV \*\*REQUEST FOR EXTENSION OF TIME\*\*

OWNER: INTERNATIONAL BEACH HOTEL DEVELOPMENT INC INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 3401.6

THE STEEL SHEET RETAINING WALL ON THE SOUTH SIDE OF

PROPERTY IS DETERIORATING AND RUSTED.

CASE NO: CE03020405

CASE ADDR: 3750 GALT OCEAN DR \*\*REQUEST FOR EXTENSION OF TIME\*\*

OWNER: REGENCY TOWERS S CONDO ASSOCIATION

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

BUILT NEW STORAGE UNITS ( 2X4 WOOD STUDS, DRY WALL, DOORS, ETC.) INSIDE PARKING GARAGE WITHOUT FIRST OBTAINING REQUIRED

PERMITS.

HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE01100240 CASE ADDR: 631 NE 18 AV

OWNER: STORELLI, JOHN & SUSAN

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

ENCLOSED CARPORT WITHOUT OBTAINING REQUIRED PERMITS.

NOTE: BOARD OF ADJUSTMENT CASE NO 01-47 APPEAL DENIED PERMIT APPLICATION A-0105283 FAILED ZONING.

\_\_\_\_\_\_

CASE NO: CE02120345

CASE ADDR: 3232 SW 2 AV # 107 SMITH, STEVEN M INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT TO INCLUDE:

1. ADDITION OF NEW OFFICE, WHICH INCLUDES, STRUCTURAL WOOD COLUMN, BEAMS, STAIRS AND NEW 2ND FLOOR.

FBC 104.2.5

NEW ELECTRICAL WORK, IN TWO-STORY OFFICE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE03010394

CASE ADDR: 4040 GALT OCEAN DR # 710 OWNER: FIERMAN, ESTELLE REV LIV TR INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT. THESE INCLUDE:

1. INSTALLED CORAL MARBLE SURFACE TILES ON WALLS AND

BALCONY

2. REPLACE/REPAIR DRYWALL CEILING OF KITCHEN AND BATHROOM

FBC 104.2.4

INSTALLED ALL NEW PLUMBING FIXTURES IN THE BATHROOM WITHOUT FIRST OBTAINING THE REQUIRED PERMIT.

FBC 104.2.5

NEW ELECTRICAL WORK IN BATHROOM, KITCHEN AND OTHER AREAS

WITHOUT FIRST OBTAINING REQUIRED PERMITS.

NOTE: PERMIT #03040720 DOES NOT COVER THE SCOPE OF THE WORK

CASE NO: CE03040354

CASE ADDR: 2701 E COMMERCIAL BLVD

OLECK, HAROLD F & NYDICK, ELAINE O

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.2.11

INSTALLED WALK IN COOLER WITHOUT FIRST OBTAINING REQUIRED

PERMITS.

FBC 104.2.5

NEW ELECTRICAL WORK FOR WALK IN COOLER AND LIGHT FIXTURES

WITHOUT FIRST OBTAINING REQUIRED PERMITS.

CE03042172 CASE NO: CASE ADDR: 3013 NE 20 CT

OWNER: SPRINGS, LARRY W & DEBORAH S

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 47-19.3 B.

BOAT LIFT DOES NOT CONFORM TO THIS SECTION OF THE CODE AS IT

IS MORE THAN 10% OF THE WIDTH OF WATERWAY.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MIT. THIS INCLUDES BOAT LIFT BUILT WITHOUT PERMITS.

# CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

AUGUST 26, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE03050946 CASE ADDR: 2757 NE 20 ST

OWNER: LEVINSON, ARTHUR PHILLIP

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE

BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT TO INCLUDE:

A. ADDED NEW ROOM ON THE REAR WEST SIDE OF PROPERTY

B. NEW PAVERS INSTALLED IN DRIVEWAY

\_\_\_\_\_\_

RETURN HEARING (OLD BUSINESS)

-----

CASE NO: CE02081375
CASE ADDR: 218 SW 15 ST
OWNER: HOMER, JOSEPH W VI
INSPECTOR: KENNETH REARDON

\*\*REQUEST FOR EXTENSION OF TIME\*\*

VIOLATIONS: FBC 104.9.3.1

PERMIT 96120036 FOR THE INSTALLATION OF THE BURGLAR SYSTEM, 00060045 FOR THE ELECTRICAL SERVICE CHANGE, 00062006 FOR THE INSTALLATION OF THE CENTRAL AIR CONDITIONING SYSTEM (RENEWED 11/12/02, BUT EXPIRED AGAIN), HAVE EXPIRED SINCE NO PASSING

INSPECTIONS WERE OBTAINED IN OVER 90 DAYS.

\_\_\_\_\_\_

CASE NO: CE03030662

CASE ADDR: 833 SW 30 ST \*\*REQUEST FOR EXTENSION OF TIME\*\*

OWNER: BLUE WATER PARTNERS LLC & GREEN AKERS LLC

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

REPLACING THE WINDOWS, FRONT DOORS AND KITCHEN CABINETS

WITHOUT FIRST OBTAINING A BUILDING PERMIT.

9 - 305(b)

THERE IS MISSING GRASS IN THE REAR YARD.

FBC 104.2.5

INSTALLED NEW ELECTRICAL TO THE CENTRAL AIR CONDITIONING SYSTEMS WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

FBC 104.2.11

INSTALLED FOUR NEW CENTRAL AIR CONDITIONING SYSTEMS WITHOUT

FIRST OBTAINING A MECHANICAL PERMIT.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

\_\_\_\_\_\_

#### HEARING COMPUTER SCHEDULED

\_\_\_\_\_\_

CASE NO: CE03020870 CASE ADDR: 1340 SW 35 AV

OWNER: LOUIE, CORRINA Y TR & RIEWE, STEPHEN M

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK WAS DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

- 1. CUT THE TIE BEAM AND REPLACED A DOOR AT THE SOUTH SIDE OF THE CENTER BREEZEWAY.
- 2. APARTMENT A4 HAS BEEN ILLEGALLY CONVERTED INTO TWO (2) LIVING UNITS (A4 & A4A).
- 3. THE FRONT AND REAR WALLS HAVE BEEN OPENED TO ACCOM-MODATE WALL AIR CONDITIONING UNITS IN APARTMENTS A4 AND A4A.

#### FBC 104.2.4

PLUMBING LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL AND THE EXTERIOR WALL OF THE CENTER BREEZEWAY WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

#### FBC 104.2.5

ELECTRICAL LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL, THE EXTERIOR WALL OF THE CENTER BREEZEWAY AND TO THE WALL AIR CONDITIONING UNITS IN APARTMENT A4 AND A4A WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

# FBC 104.2.11

WALL AIR CONDITIONING UNITS HAVE BEEN ADDED TO APARTMENTS A4 AND A4A WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

### 9-279(f)

A PLUMBING WASTE LINE DISCHARGES TO THE GROUND AT THE REAR EXTERIOR WALL, JUST NORTH OF THE CENTER BREEZEWAY.

#### 9-280(f)

THERE IS A MISSING ROOF DRAIN PIPE AT THE NORTH END OF THE REAR WALL OF THE BUILDING, WHICH SHOULD BE REPLACED.

# 9-280(h)(1)

THE POOL WOOD AND CHAIN LINK FENCES ARE DAMAGED AND ARE NOT BEING MAINTAINED.

### 9-280(b)

THE RAIN GUTTERS ARE RUSTED AND DAMAGED. THERE ARE MISSING WINDOW SCREENS THROUGHOUT THE BUILDING. THE DOOR, DOOR FRAME AND WALL ARE ROTTED AT THE STORAGE AREA UNDER THE NORTH STAIRWAY.

# 9-304(b)

THE PARKING LOT HAS POTHOLES AND IS NOT BEING MAINTAINED TO THE MINIMUM STANDARDS OF THIS CODE.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003 10:00AM

FBC 3401.6

THERE ARE STORED ITEMS IN THE METER ROOM. THIS IS NOT SAFE AND IS NOT ALLOWED.

9-305(b)

THERE IS MISSING GRASS AT THE SOUTHWEST CORNER OF THE BUILDING.

47-19.4 D.8.

THE DUMPSTER ENCLOSURE FENCE WALLS ARE DAMAGED AND REQUIRE

CASE NO: CE03020936 CASE ADDR: 840 SW 24 ST

OWNER: MOTIVA ENTERPRISES LLC

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.2.4

THE THREE COMPARTMENT SINK HAS BEEN INSTALLED WITHOUT FIRST

OBTAINING A PLUMBING PERMIT.

CASE NO: CE03021155 CASE ADDR: 2940 SW 12 AV HAEUSER, KIMBERLY K INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT 97050179 FOR THE WOOD FENCE AND PERMIT 99080979 FOR EIGHTEEN WINDOWS, HAVE EXPIRED SINCE NO PASSING INSPECTIONS WERE OBTAINED IN OVER 90 DAYS. THE PERMITS WERE RENEWED ON

3/18/03, BUT HAVE EXPIRED AGAIN.

\_\_\_\_\_

CASE NO: CE03021864 CASE ADDR: 2525 DAVIE BLVD

SUNLIGHT INVESTMENTS INC OWNER:

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE PARKING LOT HAS BEEN SEAL COATED AND RESTRIPPED WITHOUT FIRST OBTAINING A BUILDING PERMIT. THE PERMIT HAS BEEN

APPLIED FOR, BUT NEVER ISSUED.

CASE NO: CE03041438

CASE ADDR: 1320 SW 28 ST
OWNER: ALMENDARES, DENNIS A & ALMENDARES, DIANELIS ET AL

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

NEW WINDOWS AND THE FRONT DOOR HAVE BEEN INSTALLED WITHOUT

FIRST OBTAINING A BUILDING PERMIT.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003 10:00AM

FBC 104.9.3.1

PERMIT 00071418 FOR REROOFING HAS EXPIRED SINCE NO PASSING INSPECTION WAS OBTAINED IN OVER 90 DAYS.

\_\_\_\_\_

CASE NO: CE03050226 CASE ADDR: 1151 SW 29 ST

OWNER: A S G PROPERTIES INC INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.2.4

THE BATH FIXTURES HAVE BEEN REPLACED WITHOUT FIRST OBTAINING

A PLUMBING PERMIT.

FBC 104.2.5

THE ELECTRICAL HAS BEEN UPDATED IN THE KITCHEN AND BATHROOMS

WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

FBC 104.1

THE FOLLOWING REMODELING HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT, INCLUDING, BUT NOT LIMITED TO NEW KITCHEN AND BATH CABINETS. THIS DUPLEX HAS BEEN CON-

VERTED INTO THREE LIVING UNITS.

\_\_\_\_\_\_

CASE NO: CE03050426
CASE ADDR: 1660 SW 22 AV
OWNER: BRYAN, SCOTT L
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

BUILT A LARGE WOODED CHICKIE STRUCTURE WITHOUT FIRST

OBTAINING A BUILDING PERMIT.

-----

CASE NO: CE03051366
CASE ADDR: 1005 SW 15 AV
OWNER: BLAISEDALE INC
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE WINDOWS AND DOORS HAVE BEEN REPLACED WITHOUT FIRST

OBTAINING A BUILDING PERMIT.

-----

CASE NO: CE03060830
CASE ADDR: 524 SW 22 AV
OWNER: VISSCHER, LUCAS W
INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-281(b)

THE YARD IS OVERGROWN AND THE GRASS IS NOT BEING MAINTAINED.

FBC 104.9.3.1

PERMIT 02110795 FOR THE PATIO AND DRIVEWAY HAS EXPIRED SINCE NO PASSING INSPECTION WAS OBTAINED IN OVER 90 DAYS.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE03062564
CASE ADDR: 3129 SW 15 CT
OWNER: AKTER, NASIMA
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

ENCLOSED THE CARPORT WITHOUT FIRST OBTAINING A BUILDING

PERMIT.

-----

RETURN HEARING (OLD BUSINESS)

------

CASE NO: CE02062015

CASE ADDR: 3045 N FEDERAL HWY # 70 \*\*REQUEST FOR EXTENSION OF TIME\*\*

OWNER: GREG ALIFERIS HOLDINGS INC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. REMOVAL AND RELOCATION OF BEVERAGE BARS.
- B. DEMOLITION AND REMOVAL OF SOUTHEAST STAGE.
- C. INSTALLATION OF LIGHT VALANCE OVER DANCE FLOOR.
- D. BEVERAGE BARTOPS CHANGED AND RE-CONFIGURED.
- E. DOORWAY PASS-THRU OPENINGS IN EXTERIOR WALL SECTION.
- F. CREATION OF MAIN STAGE AREA AND REMOVAL OF HANDRAILS.
- G. CONSTRUCTION OF STORE ROOM AREA ADDITION.
- H. CONSTRUCTION OF WEST EXTERIOR WALL AND ENCLOSURE.
- I. CONSTRUCTION OF LOFT STORAGE AREA.
- J. INSTALLATION OF CONCRETE SLABS IN STORAGE AREAS.
- K. INSTALLATION OF WOOD DANCE FLOOR AREA.
- L. INSTALLATION OF SERVICE BEVERAGE BARS.
- M. CONSTRUCTION OF ROOF SECTIONS OVER ORIGINAL PARKING AREA.

# FBC 104.2.4

THERE HAVE BEEN RENOVATION, RELOCATION AND NEW INSTALLATION OF PLUMBING AND MECHANICAL RELATED ITEMS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS. THESE ITEMS INCLUDE, BUT ARE NOT LIMITED TO:

- A. REMOVAL OF PLUMBING CONNECTIONS AND CAPPING OF TIE-IN LINES.
- B. INSTALLATION OF ICE MACHINES (3).
- C. INSTALLATION OF COOLER.
- D. RELOCATION OF BEVERAGE BARS.

#### FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES, BUT IS NOT LIMITED TO:

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

- A. INTERIOR SERVICE SUB-PANEL IS BEING USED AS AIR-CONDITIONING DISCONNECT SWITCH.
- B. DANCE FLOOR AND STAGE LIGHTING INSTALLED.
- C. NUMEROUS WIRES AND CORDS EXPOSED AND NOT PROPERLY SECURED.
- D. RELOCATION OF BEVERAGE BAR WIRING AND TERMINATIONS CAPPED.
- E. INTERIOR WALL OUTLETS IN OUTSIDE BAR ADDITION NOT PER PLAN.
- F. EXTERIOR SERVICE DISCONNECT AND BUSS PANEL HAS BEEN CONCEALED BY CONSTRUCTION OF WALL ADDITION.
- G. STAGE OUTLETS RELOCATED.

\_\_\_\_\_

CASE NO: CE03010289 CASE ADDR: 1919 NW 19 ST

.919 NW 19 ST \*\*REQUEST FOR EXTENSION OF TIME\*\*

OWNER: PARKWAY COMMERCE CENTER LTD

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITSS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INTERIOR TENANT BUILD OUT
- B. INSTALLATION OF SECOND FLOOR OFFICES AND STAIRS

#### FBC 104.2.11

INSTALLATION OF AIR CONDITIONING SYSTEMS AND DUCT WORK WERE INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

#### FBC 104.2.4

PLUMBING SYSTEMS HAVE BEEN MODIFIED AND INSTALLATION OF NEW WORK HAS BEEN DONE WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

- A. INTERIOR BUILD OUT OF TENANT SPACE
- B. INSTALLING AND MODIFYING EXISTING PLUMBING CONNECTIONS.

# FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES, BUT IS NOT LIMITED TO:

- A. INTERIOR TENANT BUILD OUT
- B. CONNECTIONS TO MAIN POWER PANELS

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

\_\_\_\_\_\_

#### HEARING COMPUTER SCHEDULED

CASE NO: CE02061228 1225 NW 14 CT CASE ADDR: OWNER: BLYTHE, PAUL INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE

REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF FENCE

CASE NO: CE02072217
CASE ADDR: 205 NW 11 AV
OWNER: MASTEN, GREGORY & CYNTHIA

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR AND EXTERIOR OF THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES,

BUT IS NOT LIMITED TO:

A. INSTALLATION OF DOORS

B. INSTALLATION OF REPLACEMENT WINDOWS

CASE NO: CE02111210
CASE ADDR: 725 NW 14 TER
OWNER: AYALA, SANDRA INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 3401.6

FAILURE TO MAINTAIN THE PROPERTY. WOOD SOFFITS, FASCIA BOARDS, ROOF STRUCTURE, EXTERIOR DOORS AND ELECTRICAL

ELEMENTS REQUIRE REPAIR OR REPLACEMENT.

\_\_\_\_\_\_

CE03021874 CASE NO: CASE ADDR: 1716 NW 8 PL OWNER: BLAKE, MOSES INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: 47-20.13 A.

PARKING AREA IS NOT BEING MAINTAINED.

47-21.8

GROUND COVER IS NOT BEING MAINTAINED AND HAS PATCHES

OF BARE SAND.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003 10:00AM

6-34

THERE ARE MORE THAN THREE (3) DOGS BEING KEPT AT THIS LOCATION, WHICH CONSTITUTES A KENNEL.

THERE ARE MISSING AND TORN SCREENS IN THE WINDOWS OF THIS LOCATION.

9-280 (b)

THERE ARE DOORS AND WINDOWS WHICH ARE NOT WEATHER AND WATER TIGHT AND RODENT PROOF.

9-280(h)(1)

FENCE AT THIS LOCATION IS NOT BEING MAINTAINED AND HAS BROKEN, BENT OR MISSING SECTIONS.

9-306

WALLS ARE DIRTY AND PAINT IS CHIPPING AND PEELING ON BUILDING.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF CONCRETE PARKING AREAS
- B. INSTALLATION OF REPLACEMENT DOORS
- C. INSTALLATION OF CHAIN LINK FENCING
- D. INSTALLATION OF CONCRETE BLOCK WALLS

FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATION OF EXTERIOR WOOD STRUCTURES INCLUDING SOFFITS, FASCIA AND ROOF.

CASE NO: CE03030070 CASE ADDR: 2158 NW 6 CT

NEW LIFE CHRISTIAN FELLOWSHIP INC OWNER .

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIM-ITED TO:

- A. INSTALLATION OF CHAIN LINK FENCING
- B. INSTALLATION OF CANVAS CANOPIES.

#### CODE ENFORCEMENT BOARD

# CITY COMMISSION MEETING ROOM - CITY HALL

AUGUST 26, 2003 10:00AM

\_\_\_\_\_\_

CASE NO: CE03032545

CASE ADDR: 600 TENNIS CLUB DR

OWNER: THE TENNIS CLUB WINGFIELD CONDOMINIUM INC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF A LOFT & STAIRS IN MAINTENANCE AREA
- B. INSTALLATION OF REPLACEMENT GARAGE DOOR
- C. INSTALLATION OF NON-RATED DOOR ASSEMBLY TO RAQUETBALL ROOMS

FBC 3401.6

FAILURE TO MAINTAIN THE PROPERTY. AN ILLEGAL CONVERSION HAS TAKEN PLACE BY CHANGING THE USE OF THE ORIGINAL DESIGNED FACILITIES.

FBC 704.2

A FIRE SEPARATION OF ONE (1) HOUR IS REQUIRED BETWEEN THE MAINTENANCE AREA GARAGE (SHOP) AND THE RAQUETBALL ROOMS (EXERCISE ROOMS).

FBC 104.9.4.2

ORIGINAL APPROVED BUILDING PLANS AND SPECIFICATIONS WERE NOT FOLLOWED.

\_\_\_\_\_\_

CASE NO: CE03040968 CASE ADDR: 1617 NW 5 AV

OWNER: THEOPHILE, GERMAINE INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF CHAIN-LINK FENCING

B. ENCLOSURE AND ADDITION TO EXISTING RESIDENCE

CASE NO: CE03041988

CASE ADDR: 1441 N ANDREWS AV
OWNER: REES, GEORGE & JANICE
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

# CODE ENFORCEMENT BOARD

# CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

- A. INSTALLATION OF REPLACEMENT DOORS
- B. INSTALLATION OF KITCHEN CABINETS
- C. INSTALLATION OF PORCH RAILINGS AND FENCING
- D. INSTALLATION OF POOL DECKING

#### FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING WINDOW/WALL UNITS AND DRYER VENTS WERE INSTALLED WITHOUT FIRST OBTAINING THE RE-

OUIRED PERMITS.

#### FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE EXTERIOR PLUMBING AND WATER FILTRATION SYSTEM AND INTERIOR SINK AND HOT WATER HEATER CONNECTIONS AND DRAIN LINES WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

#### FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO THE NEW HOT WATER HEATER, LIGHT FIXTURES, POOL EQUIPMENT AND MAIN SERVICE PANEL.

\_\_\_\_\_\_

CASE NO: CE03050328 CASE ADDR: 2300 NW 9 CT

FRONTIER PROPERTIES LLC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF ASPHALT DRIVEWAY INSTALLTION OF KITCHEN CABINETS

\_\_\_\_\_\_

CASE NO: CE03050697 CASE ADDR: 1118 NW 19 ST RODRIGUEZ, MARIA D INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF CONCRETE DRIVEWAY AND PARKING AREA

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE03051246 CASE ADDR: 1413 NW 3 AV OWNER: HERUBIN, SCOTT INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF DOORS AND WINDOWS
- B. INSTALLATION OF KITCHEN AND BATH CABINETS

FBC 104.2.11

INSTALLATION OF AIR CONDITIONING WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING AND FIXTURES WITHOUT FIRST OBTAINING REQUIRED PERMITS.

- A. INSTALLATION OF BATHROOM FIXTURES
- B. INSTALLALTION OF HOT WATER HEATERS
- C. INSTALLATION OF KITCHEN FIXTURES

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03052245 CASE ADDR: 1613 NW 6 AV OWNER: YOHANNA, AUDREY INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF REPLACEMENT DOORS
- B. INSTALLATION OF REPLACEMENT WINDOWS
- C. INSTALLATION OF KITCHEN CABINETS
- D. INSTALLATION OF ROOF

FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND CONNECTIONS WITHOUT FIRST OBTAINING THE RE-QUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003

10:00AM

\_\_\_\_\_\_

CASE NO: CE03062272 CASE ADDR: 1600 NW 06 AV

OWNER: 1600 NW 6 AVE LAND TR , FLEISHMAN, DOUGLAS TRSTEE INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF DRIVEWAY AND PARKING AREA B. INSTALLATION OF SPRINKLER IRRIGATION.

C. INSTALLATION OF REPLACEMENT DOORS

.\_\_\_\_\_

CASE NO: CE03070371 CASE ADDR: 1416 NW 8 AVE

SUNREALM INVESTMENT PROPERTIES OWNER:

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

A. INTERIOR REMODELING OF KITCHENS AND BATHROOMS

FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND CONNECTIONS WITHOUT FIRST OBTAINING THE RE-OUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

\_\_\_\_\_\_

CASE NO: CE03071834 CASE ADDR: 721 NE 5 TER OWNER: WATERMAN, EDMUND INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF ASPHALT PAVED PARKING LOT

18-27(a)

GRASS/PLANT OVERGROWTH, RUBBISH, TRASH AND DEBRIS ON PROPERTY AND/OR SWALE.

# CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL AUGUST 26, 2003 10:00AM

47-21.8

GROUND OR LAWN COVER MISSING.

9-306

STRUCTURE NOT BEING MAINTAINED.

\_\_\_\_\_\_

CASE NO: CE03071943 CASE ADDR: 1139 NW 5 AV

OWNER: WILLIAMS, HARRY & KAREN

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.2.11

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF AIR CONDITIONING UNITS AND EQUIPMENT.

FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATED AND EXPOSED WIRING AND ELECTRICAL EQUIPMENT.

.-----

CASE NO: CE03080155
CASE ADDR: 439 NW 18 AVE
OWNER: CORZO, JOSE A
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OR THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-

CLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS
B. INSTALLATION OF REPLACEMENT DOORS
C. INSTALLATION OF KITCHEN CABINETS

D. INTERIOR DRYWALL REPAIRS

-----

CASE NO: CE99061409 CASE ADDR: 1119 NW 11 PL

OWNER: GRANT, IRVIN GEORGE & CAMPBELL, WILLIAM G.

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF WINDOW SECURITY BARS